

SA-50 Plus Firmware update

Ver:12

Svn:2645

Date:2017.09.29

Firmware updates and changes:

- 1.The firmware updates solves the problem that all optical input source's frequency will maybe recognize as 88.2KHZ automatically which will cause abnormal sound.
- 2.Performance updates Improve the system stability.
3. This firmware update contains Ver:10 version update changes:
 - 1,Solving memory leak of Demuxer MAP3,ALAC issue.
 - 2,No noise now if playback APE music file from NTFS U-disk.
 - 3,Performance updates Improve the system stability.

Firmware update by U-Disk : Save rom.upd file of player firmware into U-Disk root directory.Powering on the set .please press function button until screen shows'NO USB'.Then plug U-Disk into SA-50 plus to automatically update.When screen appear 100%,update finish.

Warning: When starting the firmware upgrade ,please do not power off or any operation to the player until the upgrade is complete.